



SERVICE LETTER

FOR THE COMPOSITE REPAIR

ON THE MODEL 301 TANK STRUCTURE

FOR ACTUATOR MOUNT ATTACHMENT HOLES

Document No.: Date: Used On: SL2008-008 November 11, 2008 Simplex Model 301 Installed on the Eurocopter Model SA-365N1, AS-365N2 and AS-365N3 per Simplex STC No. SH8801SW-D

Reviewed by: J

Tony Proger Simplex Engineering

Approved by Director of Engineering

Approved by:

Signed For:

Joel Rodriguez Manufacturing Manager



Aviation Mission Equipment

No: SL 2008-008 Date: November 11, 2008 Page 2 of 10

Log of Revisions

Rev.	Description of Revision	Date	Approved
I/R	Initial Release	November 11, 2008	SJF



Aviation Mission Equipment

No: SL 2008-008 Date: November 11, 2008 Page 3 of 10

SYSTEM MODELS AFFECTED:

Model 301 Fire Attack System

PART NUMBERS AFFECTED:

301-000000-000

SERIAL NUMBER EFFECTIVITY:

<u>S/N</u>	MODEL NUMBER	DESCRIPTION

N/A 301-000000-000 Model 301 Fire Attack System

FAA APPROVAL:

N/A No certification basis of modification

MANPOWER:

Eight (8) MHRS (Estimated)

COMPLIANCE:

N/A

MATERIALS:

QTY	PART NUMBER	DESCRIPTION
A/R	789-7775-25	Vinyl Ester Resin (Hexion)
A/R	HI-POINT 90	Methyl Ethyl Ketone Peroxide (Crompton Corp)
8	751010 (Simplex P/N)	Carbon Fiber (Ø6.0 inch patch, Hexcel 282)
A/R	751037 (Simplex P/N)	732 RTV (Dow Corning)

The information contained in this letter is proprietary to Simplex Manufacturing Co. Inc. Disclosure, reproduction, or use of this data for any purpose other than the operation and maintenance of the Simplex Manufacturing System is forbidden without prior written authorization from Simplex Manufacturing Co. Inc., Portland, Oregon.



Aviation Mission Equipment

No: SL 2008-008 Date: November 11, 2008 Page 4 of 10

SPECIAL TOOLS:

80 grit sandpaper Acetone Die-grinder and burrs Bristle roller Squeegee

WEIGHT AND BALANCE:

None

ELECTRICAL LOAD DATA:

None


PUBLICATIONS AFFECTED:

None



No: SL 2008-008 Date: November 11, 2008 Page 5 of 10

ACCOMPLISHMENT INSTRUCTIONS:



Note:

The door shaft spans the length of each dispersal door and is supported at each baffle with a bearing ring. The tank outer shell has a ball bearing assembly supporting the end connection of the door hydraulic actuator. The door shaft is secured to the door actuator with a cap, plug, adapter shaft, back-up plate, actuator mount, and nylon ball bearings.

- 1. Disconnect and remove the hydraulic actuator assembly from tank external structure.
- 2. With a pen, mark the tank with the outline of the existing Actuator Mount while still mounted to the tank structure.

Note: Marking will be used to define the angle of the new Actuator Mount when installed.

3. Remove the Actuator Mount, Back-up Plate, (2X) Shaft Cap and all attaching hardware (reference Figure 1.1).

Note: Do not discard hardware.

The information contained in this letter is proprietary to Simplex Manufacturing Co. Inc. Disclosure, reproduction, or use of this data for any purpose other than the operation and maintenance of the Simplex Manufacturing System is forbidden without prior written authorization from Simplex Manufacturing Co. Inc., Portland, Oregon.



No: SL 2008-008 Date: November 11, 2008 Page 6 of 10

- 4. Prepare inside surface of tank at the actuator hole locations.
 - a. Grind tank on the inside to feather the edge of the skin for an area at least 2 inches per Figure 1.2.
 - b. Using 80 grit sandpaper, thoroughly sand the area around the repair for at least 2 inches beyond the ground feathered edge area.




FIGURE 1.2 - Preparation of Skin

c. Clean the interior surface that has been ground and sanded with acetone at least 3 times, wiping with a clean, oil-free rag. Ensure acetone is completely evaporated prior to application of Carbon Fiber fabric (approximately 5 minutes).



5. Prepare resin/catalyst mixture.

Mixing for Use:

- a. Pour an appropriate amount of un-catalyzed Vinyl Ester Resin, P/N 789-7775-25, out in a clean mixing bucket.
- b. Determine, from Table 1.1a or 1.1b below, the appropriate amount of MEKP HI-POINT 90 Catalyst. This is 2% catalyst by volume. Add this amount of catalyst and mix thoroughly.
- c. Pot life of catalyzed mixture is approximately 35 minutes from addition of the catalyst. If mixture begins to stiffen noticeably, discard remainder of catalyzed batch.

Table 1.1a Addition of Catalyst (US Units)

Quantity of Resin		Cat	talyst
		Min(cc)	Max (cc)
0.3	cup	1.1	1.3
0.5	cup	2.1	2.6
0.8	cup	3.2	3.9
1.0	cup	4.3	5.2
1.5	cup	6.4	7.8
2.0	cup	8.5	10.4
3.0	cup	12.8	15.6
1.0	qt	17.0	20.8
2.0	qt	34.0	41.6
3.0	qt	51.1	62.4
1.0	gal	68.1	83.2

Table 1.1b Addition of Catalyst (SI Units)

Quantity of Resin			
		Catalyst	
		Min(cc)	Max (cc)
0.1	liter	1.8	2.2
0.2	liter	3.6	4.4
0.3	liter	5.4	6.6
0.4	liter	7.2	8.8
0.5	liter	9.0	11.0
0.6	liter	10.8	13.2
0.7	liter	12.6	15.4
0.8	liter	14.4	17.6
0.9	liter	16.2	19.8
1.0	liter	18.0	22.0
1.5	liter	27.0	33.0
2.0	liter	36.0	44.0
2.5	liter	45.0	55.0
3.0	liter	54.0	66.0
3.5	liter	63.0	77.0
4.0	liter	72.0	88.0

The information contained in this letter is proprietary to Simplex Manufacturing Co. Inc. Disclosure, reproduction, or use of this data for any purpose other than the operation and maintenance of the Simplex Manufacturing System is forbidden without prior written authorization from Simplex Manufacturing Co. Inc., Portland, Oregon.



- 6. Apply resin mixture to Carbon Fiber fabric (four (4) layers for each repair).
 - a. When used with fabrics, total wet-out of all the fabric is required. Air bubbles should be kept to a minimum by rolling with a bristle roller or similar device.
 - b. As much excess resin as possible must be removed from the lay-up by squeegee or similar device.
 - c. Inspect for full wet-out of fabric, excessive presence of air bubbles, and pooling of excess resin

Note:

It is desirable for a complete layup to be made at one time, with no plies being laid up over cured layers.

- 7. Apply Carbon Fiber patches over the existing actuator attachment hole pattern. Apply all layers with 0° or 90° orientation in reference to the tank structure.
- 8. Remove excess resin from fabric prior to hardening with a brush, squeegee or other means.
- 9. Allow layup to cure for 24 hours.
- 10. When layup is fully cured, cut out existing Ø1.50 inch hole for Actuator Mount, P/N 301-604003-002.
- 11. Using Actuator Mount, P/N 301-604003-002, match drill the tank structure 4X Ø0.250 0.254 inch to match the holes in the Actuator Mount. <u>Ensure the mount is at the same angle as</u> <u>the previous actuator mount (approximately 30°).</u> Location of the Actuator Mount must match the profile marked on the tank structure (reference Step 2).




FIGURE 1.3 - Door Actuators




FIGURE 1.4 - Door Actuator and Shaft Assembly

- 12. Reinstall the Actuator Mount, Back-up Plate, (2X) Shaft Cap and all attaching hardware (reference Figure 1.4).
- 13. Reinstall the hydraulic actuator assembly from tank external structure.

Note:

Install actuator attachment bolts with blue Loctite 242

14. Check doors for proper operation and sealing. Adjust doors per Model 301 Maintenance Manual.