



SERVICE LETTER

Service Letter Number	Simplex Model	Issue Date	Revision	Revision Date
SL 2010-005	328	April 28, 2010	I/R	January 26, 2010
Effectively	S/N 0003 through 0006			

Written By: 
 Stan Franz
 Director of Engineering

Approved By: 
 Stan Franz
 Director of Engineering

Subject: Hydraulic back pressure repair

Applicability: This service letter is applicable to Simplex Manufacturing Model 328 Fire Attack Systems installed on Kamov KA-32 series rotorcraft.

Parts Effected: 000-152803-000 Hydraulic Power Unit Assembly

References: Follow instructions in the following manuals where applicable to avoid damage to system while performing procedures in this service letter.

- Simplex Model 328 Maintenance Manual (MM) Document Number 328-102005-001.
- Simplex Model 328 Installation Manual Document Number 328-102002-001.

Purpose: The service letter provides instructions on how to remove the internal components of the pilot operated check valves in the hydraulic pumps housing as well as replace the cartridge assembly for the front and rear hydraulic stop solenoids.

Compliance: Compliance of this service letter is required for 328 operators. See S/N effectively.

