



SIMPLEX Mfg

Aviation Mission Equipment


SERVICE LETTER

HOVER PUMP BUMPER REPLACEMENT

ON THE SIMPLEX MODEL 301 HOVER PUMP

Document No.: SL2010-004
Date: March 23, 2010
Used On: Simplex Model 301

Approved by: _____


Tim Pyle
Sustaining Engineering and QA Manager
Simplex Mfg.



Log of Revisions

<u>Rev.</u>	<u>Description of Revision</u>	<u>Date</u>	<u>Approved</u>
I/R	Initial Release	March 23, 2010	TWP



SYSTEM MODELS AFFECTED:

Model 301 Fire Attack System (FAS)

SERIAL NUMBER EFFECTIVITY:

<u>S/N</u>	<u>PART NUMBER</u>	<u>DESCRIPTION</u>
N/A	301-704020-001	HOVER PUMP

FAA APPROVAL:

N/A

MANPOWER:

1/2 MHRS (Estimated)

COMPLIANCE:

Optional

SPECIAL TOOLS:

None

MATERIALS:

Bumper P/N 301-704047-001

WEIGHT AND BALANCE:

None



ELECTRICAL LOAD DATA:

None

PUBLICATIONS AFFECTED:

None

ACCOMPLISHMENT INSTRUCTIONS:

Step	Description
1	Remove four (4) 3/8" bolts and lock washers from bottom screen. See Figure 1-1. Retain hardware for re-installation
2	Remove screen P/N 301-704036-001. See Figure 1-1
3	Removed damaged bumper.
4	Re-install new bumper and screen using hardware retained from step 1.
5	Replacement is completed.




Figure 1-1